## **ABSTRACT OF THE DISCLOSURE**

A method for manufacturing lustrous rubber includes:

- Step 1: choose rubber of different colors;
- Step 2: add 1-100g pearl pigment to each 1kg rubber;
- 5 Step 3: mix the above combination;
  - Step 4: cool the above mixture for 2 hours;
  - Step 5: cut the above mixture into grains;
  - Step 6: vulcanize and extrude the above grains for 4 minutes 30 seconds to 5 minutes 30 seconds;
- Step 7: the lustrous rubber is finished.

Thus, lustrous colorful rubber can be manufactured through the above 7 steps, and figures can be produced too.